

Northbrook Division 333 Pfingsten Road Northbrook, IL 60062-2096 USA www.ul.com tel: 1 847 272 8800 fax: 1 847 272 8129 Customer service: 1 877 854

File E205607 Vol 1 Issued: 2002-06-19 Revised: 2005-09-09

FOLLOW-UP SERVICE PROCEDURE

(TYPE R)

COMPONENT - AUXILIARY DEVICES

(NKCR2,NKCR8)

Manufacturer: ZHEJIANG CHINT ELECTRICS CO LTD

(111876-001) CHINT INDUSTRIAL ZONE

WENZHOU,

ZHEJIANG 325604 CHINA

Applicant: SAME AS MANUFACTURER

(111876-001)

Recognized Company: SAME AS MANUFACTURER

(111876-001)

This Procedure authorizes the above Manufacturer to use the marking specified by Underwriters Laboratories Inc. only on products covered by this Procedure, in accordance with the applicable Follow-Up Service Agreement.

The prescribed Mark or Marking shall be used only at the above manufacturing location on such products which comply with this Procedure and any other applicable requirements.

The Procedure contains information for the use of the above named Manufacturer and representatives of Underwriters Laboratories Inc. and is not to be used for any other purpose. It is lent to the Manufacturer with the understanding that it is not to be copied, either wholly or in part, and that it will be returned to Underwriters Laboratories Inc. upon request.

This PROCEDURE, and any subsequent revisions, is the property of UNDERWRITERS LABORATORIES INC. and is not transferable.

UNDERWRITERS LABORATORIES INC.

Sajeev Jesudas

Chief Operating Officer

ML FILE NO. E303503

Issued: 2007-01-31 Revised: 2008-06-10

MULTIPLE RECOGNITION
of
AUXILIAR Y DEVICES - COMPONENT
(NKCR2, NKCR8)
for

[250431-001] ELECTRICAL & ELECTRONIC CONTROLS INC

Basically Recognized for:

[111876-001] ZHEJIANG CHINT ELECTRICS CO LTD (NBK)

Basically Recognized products covered by Procedure and/or Reports under File No. E205607, Volume 1

Products Covered	Report Date	Basic Applicant's (Supplier's) Product Designation	Multiple Listee's Product Designations
Thermal overload relay	2002-06-19	NR2-25-Z	ECX463A
	2002 00 15	NR2-25-Z	ECX63-1A
		NR2-25-Z	ECX-1-1.6A
		NR2-25-Z	ECX-1.25-2A
		NR2-25-Z	ECX-1.6-2.5A
		NR2-25-Z	ECX-2.5-4A
		NR2-25-Z	ECX-4-6A
		NR2-25-Z	ECX-5.5-8A
		NR2-25-Z	ECX-7-10A
		NR2-25-Z	ECX-9-13A
		NR2-25-Z	ECX-12-18A
		NR2-25-Z	ECX-17-25A
		NR2-36-Z	ECX-23-32A
		NR2-36-Z	ECX-28-36A
		NR2-93-Z	ECX95-23-32A
		NR2-93-Z	ECX-30-40A
		NR2-93-Z	ECX-37-50A
		NR2-93-Z	ECX-48-65A
		NR2-93-Z	ECX-63-80A
		NR2-93-Z	ECX-80-93 ^A
Manually operated switches	2004-05-14	NP2	EXT-ST
Indicator	2004-06-28	ND16	B22-LED

LITERATURE IS IDENTICAL TO BASICS

MARKING: Same as that described in Follow-Up Service Procedure and/or Report except for

Multiple Listee's name, ML Tradename, when applicable, and product designation.

UL INSPECTION CENTER HANGZHOU - 325